
| City of Baltimore Wet Smoke and Dyed | Page 1 of 1 | |
|---|---------------------------------------|--|
| Sewershed: Gwynns Falls | Company: Savin | Date: 9/1/2009 |
| Test to be performed: Smoke Dyed Water X | Ground Condition: Dry ✓ Damp ☐ Wet ☐ | Supervisor: JAW |
| Manhole_ID: S04MM_005MH | Test ID: <u>D1032-023016</u> | Notification Made: NA (Residents, Fire, 311) |

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



| Defect Loc | Obs_ClockFrom | Obs_ClockTo | Observation | Obs_Remarks |
|-------------|---------------|-------------|------------------|----------------------|
| 0 | | | Start of Survey | |
| 0 | | | Manhole | S04MM_002MH |
| 0 | | | Water Level | |
| 97.59999847 | 09 | | Tap Factory | 2304 TUCKER LN |
| 97.59999847 | | | Dye Test Visible | FROM 2304 CLEAN OUT |
| 97.59999847 | | | Dye Test Visible | FROM 2304 DOWN SPOUT |
| 97.59999847 | | | Abandoned Survey | DYE FLOOD COMPLETED |